


1999

Status & Condition

of the Arizona Highway System

Present Serviceability Ratings




Present Serviceability Rating

The Present Serviceability Rating (PSR) is derived from readings taken by a mechanical device that measures deviations in the roadway surface. The deviations provide a measure of the smoothness or roughness of the pavement. The PSR rates the pavement condition on a scale from 0 to 5, with 0 being very poor (undriveable) and 5 being excellent (new surface). The pavement rating ranges and the conditions they indicate are as follows:







PSR	Condition	Indication
0 - 1.0	Very Poor	Extremely deteriorated
1.1-2.0	Poor	Has large pot holes, cracking, distress
2.1-3.0	Moderate	Barely tolerable for high speed traffic
3.1-4.0	Good	Relatively Smooth
4.1-5.0	Excellent	New or superior

The PSR data is mapped at the county level and inserts are used where appropriate.

1999 PRESENT SERVICEABILITY RATING ON THE ARIZONA STATE HIGHWAY SYSTEM






PSR in Arizona


-  4.1 - 5.0 = Excellent
-  3.1 - 4.0 = Good
-  2.1 - 3.0 = Moderate
-  1.1 - 2.0 = Poor
-  0 - 1.0 = Very Poor
-  5.1 - 9.9 = Unpaved

[click on county name \(yellow outlined area\) to go to county map](#)


ROAD CONDITIONS IN APACHE COUNTY




ROAD CONDITIONS IN COCHISE COUNTY





ROAD CONDITIONS IN COCONINO COUNTY









ROAD CONDITIONS IN GILA COUNTY




ROAD CONDITIONS IN GRAHAM COUNTY






Present Serviceability Rating

-  4.1 - 5.0 = Excellent
-  3.1 - 4.0 = Good
-  2.1 - 3.0 = Moderate
-  1.1 - 2.0 = Poor
-  0 - 1.0 = Very Poor
-  Unpaved




ROAD CONDITIONS IN GREENLEE COUNTY





ROAD CONDITIONS IN LA PAZ COUNTY









ROAD CONDITIONS IN MARICOPA COUNTY





INSET ROAD CONDITIONS IN THE PHOENIX METROPOLITAN AREA



Present Serviceability Rating

-  4.1 - 5.0 = Excellent
-  3.1 - 4.0 = Good
-  2.1 - 3.0 = Moderate
-  1.1 - 2.0 = Poor
-  0 - 1.0 = Very Poor
-  Unpaved

INSET ROAD CONDITIONS IN CENTRAL PHOENIX



Present Serviceability Rating

4.1 - 5.0 = Excellent

3.1 - 4.0 = Good


2.1 - 3.0 = Moderate

1.1 - 2.0 = Poor


0 - 1.0 = Very Poor

Unpaved



ROAD CONDITIONS IN MOHAVE COUNTY









ROAD CONDITIONS IN NAVAJO COUNTY





ROAD CONDITIONS IN PIMA COUNTY





Present Serviceability Rating

-  4.1 - 5.0 = Excellent
-  3.1 - 4.0 = Good
-  2.1 - 3.0 = Moderate
-  1.1 - 2.0 = Poor
-  0 - 1.0 = Very Poor
-  Unpaved







INSET ROAD CONDITIONS IN THE TUCSON METROPOLITAN AREA





ROAD CONDITIONS IN PINAL COUNTY









Present Serviceability Rating

-  4.1 - 5.0 = Excellent
-  3.1 - 4.0 = Good
-  2.1 - 3.0 = Moderate
-  1.1 - 2.0 = Poor
-  0 - 1.0 = Very Poor
-  Unpaved


ROAD CONDITIONS IN SANTA CRUZ COUNTY



Present Serviceability Rating

-  4.1 - 5.0 = Excellent
-  3.1 - 4.0 = Good
-  2.1 - 3.0 = Moderate
-  1.1 - 2.0 = Poor
-  0 - 1.0 = Very Poor
-  Unpaved

ROAD CONDITIONS IN YAVAPAI COUNTY



ROAD CONDITIONS IN YUMA COUNTY

